ABTRACT

In a method for controlling temperatures in a semiconductor manufacturing apparatus including a reaction chamber and a plurality of heating sources, a set of power ratios to be fed to the heating sources is determined for each of two or more selected temperatures. Then, a temperature of the reaction chamber is controlled by performing power control on the heating sources based on at least one set of power ratios obtained.

- 30 -

10

5